
















Assembly Instructions










Specifications: L1200*W600*H1030



Sr.	Sketch	Qty
A(20")		6
B		74
C(Ø15*12)		74
D		24
E (M4*40)		24
F(M3. 5*30)		13
G(M3. 5*20)		40
H (M4*15)		36
I		9
J		4
K		4
L		4
M		1




1  ×1	2  ×1	3  ×1	4  ×1
5  ×4	6  ×1	7  ×1	8  ×1
9  ×1	10  ×2	11  ×6	12  ×6 P. 3/17


13  × 3	14  × 3	15  × 1	16  × 1
17  × 1	18  × 3	19  × 3	20  × 3
21  × 3			P. 4/17

step 1

B



11pcs





step 2

C



6pcs





step 3

C



2pcs





step 4

C




3pcs




step 5

F




M3. 5*30

4pcs




step 6

B



B

18pcs




step 7


C



9pcs



step 8




step 9

C




9pcs




step 10

B




9pcs




C		9pcs
---	---	------

step 11




G		20pcs
---	---	-------

step 12




G		20pcs
J		4pcs
K		4pcs



G		16pcs
----------	---	--------------

M3. 5*20


step 13



A		6pcs
H		36pcs

M4*15

step 14




step 15

B




30pcs



step 16

F




M3. 5*30

9pcs


I




9pcs




step 17

D		12pcs
E	 M4*40	12pcs



step 18





step 19

C





12pcs



P. 14/17



step 20

D		12pcs
E	 M4*40	12pcs




step 21

C		6pcs
---	---	------



step 22





step 23


C



18pcs



step 24



step 25

G	 M3. 5*20	4pcs
L		4pcs
M		1pc

